Anemometer (CMM, CFM) Humidity meter, Light meter Type K Thermometer

Model: LM-8010 *ISO-9001, CE, IEC1010*





The Art of Measurement

Anemometer, Hygrometer, Light Meter, Thermometer

Model : LM-8010

FEATURES

t	EATURES .
*	5 in 1 professional measuring instrument: Anemometer,
	Air flow, Hygrometer, Thermometer, and Light meter.
	Tiny bone shape with lightweight and small size case design
	are suitable for handling with one hand.
*	Wristlet design provides extra protection to the instrument
	especially for user one hand operation.
*	Low-friction ball bearing mounted wheel design provides
	high accuracy at high and low air velocity.
*	Exclusive photo diode and color correction filter light sensor,
	spectrum meets C.I.E. photopic.
*	High precision thin-film capacitance humidity sensor with
	fast response to the humidity changes.
*	Standard type K (NiCr-NiAl) thermocouple input jack
L	suitable for all kinds of type K probe.
*	Built- in microprocessor circuit assures excellent
L	performance and accuracy.
*	Concise and compact buttons arrangement, easy operation.
*	Memorize the maximum and minimum value with recall.
*	°C/°F selectable by pressing button on the front panel.
*	Lux/Feet-candle selectable by pressing button on the front
	panel.
*	Air velocity measuring units selectable by pressing button on
	the front panel for five kinds of units.
*	Air flow (CFM. CMM) measurement can set the desired area
	dimension.
*	Multi channel display for relative humidity and temperature
	measured values or air velocity and temperature measured
	values at the same time.
*	Zero button design makes light meter calibration.
*	Hold function to freeze the current reading value.

GENERAL SPECIFICATIONS

Display	8 mm LCD display		
Measurement	Anemometer, Humidity, Temperature,		
	Light, Air flow (CFM/CMM).		
Operating	Max. 80% RH.		
Humidity	Wax. 0070 KH.		
Operating	0 to 50° C (32 to 122° F)		
Temperature	0 10 30 0 (32 10 122 1)		
Over Input	Indication of " "		
Display	Tridication of		
	004D DC 0V battary (Hagyay duty typa)		
Power Supply Power	O06P DC 9V battery (Heavy duty type) Approx. DC 6.2 mA		
	Approx. DC 6.2 IIIA		
Consumption	1/On (bottom impliced d)		
Weight	160g (battery included)		
Dimension	HWD:		
	156x60x33 mm		
0, ,	6.14x2.36x1.29 inch		
Standard	Instruction Manual		
Accessory			
Optional	Carrying case, CA-52A, CA-06.		
Accessories	Temperature probe (TP-01, TP-02A,		
	TP-03. TP-04):		
	TP-01 * Max. short-tern operating		
	Temperature: 300 $^{\circ}$ C (572 $^{\circ}$ F).		
	* It is an ultra fast response		
	naked-bead thermocouple		
	TP-02A * Measure Range: -50 °C to 900 °C.		
	* Dimension:10cm tube, 3.2mm Dia.		
	TP-03 * Measure Range: -50 $^{\circ}$ C to 1200 $^{\circ}$ C.		
	* Dimension: 10cm tube, 8mm Dia.		
	TP-04 * Surface temperature probe.		
	* Measure Range: -50 °C to 400 °C.		

ELECTRICAL SPECIFICATION (23 \pm 5°C)

Measurement		Range	Resolution
Air velocity	ft/min	80 to 5,910 ft/min	1 ft/min
	m/s	0.4 to 30.0 m/s	0.1 m/s
	km/h	1.4 to 108.0 km/h	0.1 km/h
	MPH	0.9 to 67.0 mile/h	0.1 MPH
	knots	0.8 to 58.3 knots	0.1 knots
	Temperature	32 to 122 °F	0.1 °F
	(thermister)	0 to 50 ℃	0.1 ℃

Measureme	nt	Range	Resolution
Air flow	CMM	54,000 CMM	0.001 to 1
	cube meter/mir	ו	CMM
	CFM	1,908,400 CFM	0.001 to 100
	cube feet/min		CFM

Measurement		Range	Resolution
Humidity % RH		10 to 95 %RH	0.1 %RH
	Temperature	32 to 122 °F	0.1 °F
	(thermister)	0 to 50 ℃	0.1 ℃

Measurement		Range	Resolution
Light	Lux	0 to 2,200 Lux	1 Lux
		1,800 to 20,000 Lux	10 Lux
* auto range	Ft-cd	0 to 204.0 Fc	0.1 Ft-cd
_		170 to 2,000 Fc	1 Ft-cd

Measurement	Range	Resolution
Temperature (Type K)	-148 to 2,372 °F	0.1 °F
	-100 to 1,300 ℃	0.1 ℃

Measurement	Range	Accuracy
Air velocity	80 to 5,910 ft/min	
	0.4 to 30.0 m/s	\leq 20 m/s : ± 3% F.S.
	1.4 to 108.0 km/h	> 20 m/s : ± 4% F.S.
	0.9 to 67.0 mile/h	
	0.8 to 58.3 knots	
	32 to 122 °F	± 2.5 °F
	0 to 50 ℃	± 1.2 ℃

Remark :

ft/min : feet per minuteMPH : miles per hourm/s : meters per secondknots : nautical miles per hourkm/h : kilometers per hourFt-cd : feet candle

Measurement	Range	Accuracy
Humidity	10 to 95 %RH	< 70% RH :
		± 4 %RH
		<i>≧70% RH :</i>
		: ± (4%rdg + 1.2 %RH)
	32 to 122 °F	± 2.5 °F
	0 to 50 ℃	± 1.2 ℃

Measurement	Range	Accureacy	
Light	0 to 20,000 Lux	± 5% rdg	± 8 dgt
	0 to 2,000 Fc		

Measurement	Range	Accuracy
Temperature	-148 to 2,372 °F	± (1% rdg + 2°F)
(Type K)	-100 to 1,300 ℃	± (1% rdg + 1°C)

Measurement Area setting	
CMM	0.001 to 30.000 meter square
CFM	0.01 to 322.92 feet square