



Model WT-10 Waterproof Thermometer

◆ Features

- 2.75" (70mm) stainless steel stem
- °F/°C switchable ranges of -40 to 392°F (-40 to 200°C)
- Min/Max recall of high and low temperatures
- Hold and Auto-Off
- Digital display with 0.1° resolution
- Complete with one LR44 button battery

◆ Instructions

Power

- Press the ON/OFF Key to turn power on or off

°F/°C

- Press the °F/°C key to select the temperature units

Hold/Min/Max

- Press the MODE key one to hold the reading in the display. "HOLD" will appear on the display.
- Press the "MODE" key a second time to display the stored maximum reading. "MAX" will appear on the display.
- Press the "MODE" key a third time to display the stored minimum reading. "MIN" will appear on the display.
- Press the "MODE" key a fourth time to return to normal operation.

Min/Max Memory Reset

- With "MIN" or "MAX" in the display, press and hold the "MODE" key until "---" appears. This means the memory is cleared.
- Press the "MODE" key again to return to normal operation.

Dwyer Instruments, Inc.

P.O. Box 373

Michigan City, IN 46361

Toll Free: 1-800-872-9141 or on the internet:

www.dwyer-inst.com